

Spot the differences

So, the garage has yet again a new floor. The top one of the images below is from the current situation, the one below it is from the first attempt (already 2 years ago!). Spot the differences…





Let's hope this time the cracks will not appear. Having to clear out the garage, store everything somewhere and put everything back is definitely not my idea of a good time.

On the *cobra-building front* it's a bit quiet due to lack of parts, though I could do a few jobs on the chassis and suspension I guess, but for many of them I want to be able to take measurements of the engine, gearbox and other stuff before I do them.

I have been assured that the parts will be available for collection next week, so it should not be that long before I can get cracking at a slightly higher pace.